

03500.013077.1



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

ISAO KOBAYASHI ET AL.

Appln. No.: 09/842,694

Filed: April 27, 2001

For: PHOTOELECTRIC CONVERTER,  
METHOD FOR DRIVING  
PHOTOELECTRIC CONVERTER AND  
SYSTEM HAVING PHOTOELECTRIC  
CONVERTER

U.S. Patent No.: 6,867,469 B2

Issued: March 15, 2005

) Examiner: J.P. Mondt

) Group Art Unit: 2826

)

)

)

)

)

)

) June 30, 2005

Certificate  
JUL 06 2005  
of Correction

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

07/01/2005 SSITHIB1 00000104 6867469

01 FC:1811

100.00 OP

JUL 07 2005

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



John A. Krause  
Attorney for Patentees  
Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
Facsimile: (212) 218-2200

NY\_Main 509104v1

JUL 07 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only

PRINTER'S TRIM LINE

PATENT NO. : US 6,867,469 B2

DATED : March 15, 2005

INVENTOR(S) : ISAO KOBAYASHI ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 3:**

Line 57, "each" should be deleted.

**COLUMN 7:**

Line 42, "resulting in" should read --with the result--;  
Line 53, "respective" should read --respect--; and  
Line 65, "D" (second occurrence) should read --G--.

**COLUMN 9:**

Line 25, "of" should read --the--.

**COLUMN 10:**

Line 36, "the" should read --since the--.

**COLUMN 12:**

Line 34, "can" should read --can be--.

**COLUMN 13:**

Line 11, "respective" should read --respect--;  
Line 21, "of time." should read --time--; and  
Line 45, "thus" should read --the--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,867,469 B2

No. of add'l. copies  
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,867,469 B2

DATED : March 15, 2005

INVENTOR(S) : ISAO KOBAYASHI ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 1, "are" should read --is--; and  
Line 58, "some" should be deleted?

COLUMN 15:

Line 21, "electrode" should read --electrode by--; and  
Line 53, "One example" should read --Examples--.

COLUMN 16:

Line 46, "characteristic" should read --characteristics--.

COLUMN 17:

Line 12, "be" should be deleted;  
Line 20, "thus" should read --this--; and  
Line 29, "come" should read --comes--.

COLUMN 20:

Line 13, "got" should read --enter--.

COLUMN 21:

Line 16, "While, it has been made clear that" should read --As has been made  
clear,--; and  
Line 54, "both" should read --in both--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,867,469 B2

No. of add'l. copies  
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

**PATENT NO. :** US 6,867,469 B2

**DATED :** March 15, 2005

**INVENTOR(S) :** ISAO KOBAYASHI ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 23:**

Line 38, "mounted" should read --mounted on--; and  
Line 62, "emit" should read --emits--.

**COLUMN 24:**

Line 6, "doctors" should read --so that doctors-- and "diagnose" should read  
--make a diagnosis--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,867,469 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

NY\_Main 509104v1

→ \_\_\_\_\_  
JUL 07 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,867,469 B2

DATED : March 15, 2005

INVENTOR(S) : ISAO KOBAYASHI ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 3:**

Line 57, "each" should be deleted.

**COLUMN 7:**

Line 42, "resulting in" should read --with the result--;  
Line 53, "respective" should read --respect--; and  
Line 65, "D" (second occurrence) should read --G--.

**COLUMN 9:**

Line 25, "of" should read --the--.

**COLUMN 10:**

Line 36, "the" should read --since the--.

**COLUMN 12:**

Line 34, "can" should read --can be--.

**COLUMN 13:**

Line 11, "respective" should read --respect--;  
Line 21, "of time." should read --time.--; and  
Line 45, "thus" should read --the--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,867,469 B2

No. of add'l. copies  
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,867,469 B2

DATED : March 15, 2005

INVENTOR(S) : ISAO KOBAYASHI ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 14:**

Line 1, "are" should read --is--; and  
Line 58, "some" should be deleted?

**COLUMN 15:**

Line 21, "electrode" should read --electrode by--; and  
Line 53, "One example" should read --Examples--.

**COLUMN 16:**

Line 46, "characteristic" should read --characteristics--.

**COLUMN 17:**

Line 12, "be" should be deleted;  
Line 20, "thus" should read --this--; and  
Line 29, "come" should read --comes--.

**COLUMN 20:**

Line 13, "got" should read --enter--.

**COLUMN 21:**

Line 16, "While, it has been made clear that" should read --As has been made  
clear,--; and  
Line 54, "both" should read --in both--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,867,469 B2

No. of add'l. copies  
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,867,469 B2

DATED : March 15, 2005

INVENTOR(S) : ISAO KOBAYASHI ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 38, "mounted" should read --mounted on--; and  
Line 62, "emit" should read --emits--.

COLUMN 24:

Line 6, "doctors" should read --so that doctors-- and "diagnose" should read  
--make a diagnosis--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,867,469 B2

No. of add'l. copies  
@ 30¢ per page